

Radon Testing Health & Social Services 2017-18

As per the Radon Management Guidelines for Yukon government.

Measurements are Becquerels per cubic metre Bq/m ³ Measurements below 200 Bq/m ³ are within Health Canada guidelines.			
Facility	Highest Reading	Lowest Reading	Post Mitigation
Ross River Health Centre	70	41	N/A
Teslin Health Centre	56	30	N/A
Pelly Crossing Health Centre	148	78	N/A
Old Crow Health Centre	30	18	N/A
Haines Junction Health Centre	67	52	N/A
Faro Health Centre	266	174	
Destruction Bay Health Centre	41	26	N/A
Carcross Health Centre	67	44	N/A
Carmacks Health Centre	118	81	N/A
Haines Junction HSS Residence	104	78	N/A
Beaver Creek Health Centre	152	126	N/A
9010 Quartz Road	111	15	N/A
Mayo Health Centre	303	46	16*
Residential Facility A	259	52	33
Residential Facility B	637	69	19
Residential Facility C	25	15	N/A
Residential Facility D	97	15	N/A
Residential Facility E	256	55	
Residential Facility F	16	15	N/A
Residential Facility G	230	91	
Residential Facility H	16	15	N/A
Residential Facility I	124	15	N/A
Note: Staff of youth facilities may contact their supervisor for test result information.			

Mitigation requirements:

- Between 200 and 600 Bq/m³ within 2 years
- Over 600 Bq/m³ within 1 year

* Mitigation in 2018, initial short term test of 16 Bq/m³. Long term test to be completed winter 2018/19